

St. Joseph's College Of Education For Women

Opp. Sambasivapet 2nd Lane, Naaz Center, GUNTUR, A.P., INDIA.
(Under the Management of Society of Jesus Mary & Joseph)




7.1.4 Geo Tagged Photographs

Rain

Water

Harvesting

Rain Water Harvesting Pit





Guntur, Andhra Pradesh, India


Women's College Road, 7CWW+C65, Naaz Center Rd, Sambasiva Pet, Guntur, Andhra Pradesh 522001, India

Lat 16.296045°

Long 80.445643°

18/07/24 03:46 PM GMT +05:30

GPS Map Camera



Guntur, Andhra Pradesh, India

7CWR+QG7, Kanna Vari Thota, Guntur, Andhra Pradesh 522004, India

Lat 16.296988°

Long 80.441157°

01/08/24 10:17 AM GMT +05:30



GPS Map Camera

Waste

Water


Recycling

Using of recycled water for Plants



Utilizing reclaimed water for Plant irrigation

Re-use of Waste water




**Tanks,
Bore wells
& Sump**

Over Head Tanks



Hostel Block Water Tank



College Block Water Tank - I






Water tank distribution system

Bore well

In SJCE campus we have one bore well whenever scarcity of water then we use ground water for domestic use.



Sump



Sump and reservoirs used to storage to hold and manage water





Economical

Usage

Reduced




wastage

Economical usage /Reduced Wastage





Using sprayers for gardening is very beneficial for reducing the water usage

Sign Boards



Using a water can is Eco-Friendly way to water plants



Valves are allowing to control water flow and efficient for water usage.

Periodical Maintenance


Any leakage or repair was found immediately SJCE management takes the action to repair or maintenance.





Repair was done by our Technicians

Water Sensor Alarm



Automatic water level control system



R.O water plant



Providing clean/safe drinking water for staff and students